

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023138**Date Inspected:** 25-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for random observations relative to the work being performed.

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Zhu Lin, CWI Sun Tian Liang.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG

PCMK: X3305K-033

Weld No: 001,002

Welder: 067876

WPS-B-T-2233-ESAB

Components; OBG

PCMK: X3305K-023

Weld No: 001,002

Welder: 045240

WPS-B-T-2233-ESAB

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Zhu Lin, CWI Sun Tian Liang.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG

PCMK: TR3021TR1-001

Weld No: 004

Welder: 066673, 066674

Repair No. B-WR20755

WPS-345-SMAW-2G(2F)-Repair-1

Components; OBG

PCMK: X3305K-015

Weld No: 001,002

Welder: 067611

WPS-B-P-2212-TC-U4b-FCM-1

This Caltrans QA Inspector observed at random intervals ZPMC performing grinding of welds located in OBW Splice Plate X4241D at various locations due to contour grinding and visual indications as identified by ZPMC QC Inspectors.

This Caltrans QA Inspector observed at random intervals ZPMC performing grinding of welds located in OBW13 Splice Plate X3305K-017 at various locations due to contour grinding and visual indications as identified by ZPMC QC Inspectors.

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Xie Ming Feng, QA Zhang Qi Li .

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG 14 E

PCMK: SEG3019AH

Weld No: 001

Welder: 216086

WPS-B-P-2212-TC-U4b-FCM-1

Components; OBG 14 E

PCMK: SEG3019*

Weld No: 017

Welder: 215553

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

WPS-B-P-2212-TC-U4b-FCM-1

Components; OBG 14 E

PCMK: SEG3019E-1

Weld No: 025~048

Welder: 501946

WPS-B-P-2213-TC-U4b-FCM-1

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Xie Ming Feng, QA Zhang Qi Li.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG 14 E

PCMK: SEG3019W

Weld No: 011,013

Welder: 067877

WPS-B-T-2233-ESAB

Components; OBG 14 E

PCMK: SEG3019V

Weld No: 227

Welder: 058102, 044772

Weld Repair No. B-WR20407

WPS-345-FCAW-3G(3F)-FCM-Repair-1

Components; OBG 14 E

PCMK: SEG3019S

Weld No: 342,350,343,345,351

Welder: 058102, 044772

Weld Repair No. B-WR20407

WPS-345-FCAW-3G(3F)-FCM-Repair-1

Components; OBG 14 E

PCMK: SEG3019Q-2

Weld No: 205,207,214

Welder: 058102, 044772

Weld Repair No. B-WR20407

WPS-345-FCAW-3G(3F)-FCM-Repair-1

Components; OBG 14 E

PCMK: SEG3019N

Weld No: 266,172,295,273

WELDING INSPECTION REPORT

(Continued Page 4 of 4)

Welder: 058102, 044772

Weld Repair No. B-WR20407

WPS-345-FCAW-3G(3F)-FCM-Repair-1

Components; OBG 14 E

PCMK: SEG3019L

Weld No: 219,221

Welder: 058102, 044772

Weld Repair No. B-WR20407

WPS-345-FCAW-3G(3F)-FCM-Repair-1

Heat straightening of OBG14 East Bottom Plate at Panel Point 125 under approved Heat Straightening procedure, HSR1 (B)-465. The in process temperature was observed as 450°C. The ZPMC QC was identified as Xie Ming Feng. The approved HSR procedure stated that a maximum temperature of 650°C with 1-3 numbers of applications was allowed. The distortion that was previously measured and recorded on the HSR was Maximum 8mm.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

“No relevant conversations.”

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey 1500026784, who represents the Office of Structural Materials for your project.

Inspected By:	Leavitt,Kelly
----------------------	---------------

Quality Assurance Inspector

Reviewed By:	Riley,Ken
---------------------	-----------

QA Reviewer
